

Appropriations Requests for Legislatively Directed Spending Items

- 1. The sponsoring representative's first name: Noah
- 2. The sponsoring representative's last name: Arbit
- 3. The cosponsoring representatives' names. All cosponsors must be listed. If none, please type 'n/a.' A signed letter from the sponsor approving the co-sponsorship and a signed letter from the member wishing to co-sponsor are required. Attach letters at question #9 below.
 - n/a
- 4. Name of the entity that the spending item is intended for: Cass Lakeside Community Association
- 5. Physical address of the entity that the spending item is intended for: 4927 Greer Rd, West Bloomfield Township, MI 48324
- 6. If there is not a specific recipient, the intended location of the project or activity: n/a
- Name of the representative and the district number where the legislatively directed spending item is located: Rep. Noah Arbit, House District 20
- 8. Purpose of the legislatively directed spending item. Please include how it provides a public benefit and why it is an appropriate use of taxpayer funding. Please also demonstrate that the item does not violate Article IV, S 30 of the Michigan Constitution. Cass Lakeside Community Association is the home-owners' association representing an economically diverse neighborhood of approximately 300 homes and nearly 700 residents in northern West Bloomfield Township, bordering Waterford Township. The neighborhood is comprised of numerous islets and canals, which are connected by bridges privately owned by the neighborhood association. Almost all of the community's bridges and roads are in poor condition, but the community has struggled to pay for critical maintenance, and as it is a private HOA, has no ability to bond.

The Algonquin Avenue Bridge was originally built in 1924. After a 2022 survey, it was

deemed to be in failing condition. The bridge is no longer safe for the public to use without concern. Even more concerning is that the bridge's load capacity has been reduced to 7 tons, which does not meet the 2015 fire code requirement for fire trucks. West Bloomfield Township has indicated they may be forced to cease emergency services to this part of the neighborhood because the bridge is no longer load rated to support even the smallest West Bloomfield fire truck. Repair of the bridge will improve the safety of residents, visitors, construction workers, and first responders entering and exiting the neighborhood in northern West Bloomfield, and extend the bridge's lifespan significantly.

This \$1,000,000 appropriation to Cass Lakeside Community Association would fund half of the community's expected cost for the repair of the Algonquin Avenue Bridge.

- 9. Attach documents here if needed: Attachments added to the end of this file.
- 10. The amount of state funding requested for the legislatively directed spending item. 1000000
- 11. Has the legislatively directed spending item previously received any of the following types of funding? Check all that apply.["None"]
- Please select one of the following groups that describes the entity requesting the legislatively directed spending item: Non-profit organization
- 13. For a non-profit organization, has the organization been operating within Michigan for the preceding 36 months? Yes
- 14. For a non-profit organization, has the entity had a physical office within Michigan for the preceding 12 months? Yes
- 15. For a non-profit organization, does the organization have a board of directors? Yes
- 16. For a non-profit organization, list all the active members on the organization's board of directors and any other officers. If this question is not applicable, please type 'n/a.' President: Robert Redner; Vice President: Michael Johnson; Secretary: Debbie Zielesch; Treasurer: Cathy O'Connell; Board Members: Christopher Laduke, Josh Barstow, Ken Russel, Wendy Rupp, Steve O'Connor

17. "I certify that neither the sponsoring representative nor the sponsoring representative's staff or immediate family has a direct or indirect pecuniary interest in the legislatively directed spending item."

Yes, this is correct

- 18. Anticipated start and end dates for the legislatively directed spending item: Anticipated Year of Construction: 2028
- 19. "I hereby certify that all information provided in this request is true and accurate." Yes

Spicer	picer Bridge Inspection and Load Rating Report (September 2022)								111			
					Posting by Truck Type (Tons)				ency order	14	Derverse of Di	rock (
Bridge	Span	Width	Roadway	1-Unit	2-Unit	3-Unit	Emergency Veh	Urgency	Repair order			Contra ante puerto
1	34ft	17ft	Linwood Dr.	23	30	49	26	3	6			Coverlay
												any crack his
2	34ft	17ft	Linwood Dr.	23	30	49	26	3	8	-VT		a structure p
										-	- PIT	and surth
4	34ft	10ft	Linwood Dr.	17	20	33	20	4	12	Distour Are		
										New Love Love		Susseries and and
5	34ft	10ft	Point View Dr.	13	17	28	15	2	5		10 11	
							_	-		Martine-		12 13
6	34ft	17ft	Windside Dr.	23	30	49	26	3	7		9	
										TZH	8'	Jacob - Land
8	34ft	17ft	Auburndale Ave.	23	30	49	26	4	10	SAN / I	Automatic and Cit	Contraction of the second
										- bottom		1 -
9	34ft	17ft	Parkview Ave.	17	19	32	19	2	3	176		
										- Area	Algondult. Ave	
10	34ft	17ft	Gerundecut Dr.	15	18	29	17	2	4			
										1		
11	34ft	10ft	Prospect Dr.	12	14	23	13	3	11		6.	
												O Pointy ow Dr
12	34ft	10ft	Prospect Dr.	12	14	23	13	4	13	15	-4	and the base of the second second
											- TOUR	a stated by but the
13	34ft	10ft	Prospect Dr.	12	14	23	13	4	14	11-1	MARINE IN	State State State
										THE	2 3	
14	34ft	17ft	Gerundecut Dr.	15	17	28	17	5	15	111111		
										Salaria Ca TT		al all the second second second second
15	29ft	21ft	Greer Rd.	16	20	33	19	1	1			* The second
	Truss Bridge Posting by Axle (Tons)										Urgency Scale	Bridges
					Axle		Gross			1	Serious/Critical	7,15
3	52ft	17ft	Linwood Dr.		9		15	3	9	2 Serious/Non-Critical		5,9,10
										3	Moderate/Near Future	1,2,3,6
7	52ft	17ft	Algonquin Dr.		2	l	7	1	2	4	Intermidiate	4,8,11,12
										5	Eventual	13,14



Algonquin Dr over Woodland Lagoon STR 7

Bridge Inspection Report

2022 Cass Lake Subdivision Bridge Eng. (15 Structures)

Prepared for: Cass Lake Subdivision

August 2022 SGI Project No. 132341SG2022





Executive Summary

BRIDGE DATA

STR 7	Algonquin Drive over Woodland Lagoon
Location:	Cass Lake, MI
Year Constructed:	1924 - Estimated
Min. Vertical Clearance:	N/A
Posted Vertical Clearance:	N/A
Bridge Description	
Superstructure Type:	1-Span; Thru Truss
Abutment Type:	Concrete cantilever walls on steel piles
Pier Type:	N/A
Number of Lanes On:	Private Road; Single Lane
Number of Lanes Under:	N/A
Out-to-Out Deck Width:	14.7 ft
Bridge Length:	54.0 ft
Skew:	0°
Condition	
Deck Surface:	5 Fair: Moderate block cracking – longitudinal cracks
Joints:	N/A
Other Joints:	6 Fair: Cold joint at reference lines; signs of minor leaking
Railing:	5 Fair: Minor collision damage at Southeast bearing; several loose connectors
Sidewalks/Curbs:	N/A
Deck Bottom:	7 Good: Checks/shakes penetrate less than 5% of thickness
Deck:	7 Good: Checks/shakes penetrate less than 5% of thickness (based on deck bottom rating)
Superstructure:	3 Serious: 7" steel double c-channels with riveted 12.25"x0.25" cover plate thru-truss – hole through one c-channel at Southwest bearing, holes in gussets at Southwest, Northwest, and Northeast bearing, hole through horizontal leg of angle; steel floor beams – hole through inner gusset of floor-beam 1W on south side; 4"x10" full cut spike laminated timber slab as stringers – some splits on the bottom $\frac{1}{4}$ " of fascia stringers
Paint:	4 Poor: Significant areas of corrosion and pack rust
Section Loss:	0 Failed: Holes in gusset plates require reduction of posted load or steel repairs based on structural analysis
Bearings:	3 Serious: Considerable deterioration in bearing areas
Abutment(s):	6 Fair: Spall in SW quad – patched, but patch has delaminated and spalled off; abutments probed – soft silt, but no scour noted on inspection
Pier(s):	N/A



Slope Protection:	N/A: Structure over water
Channel/Channel Protection:	7 Good: Minor erosion of Southeast quadrant; riprap in Northwest quadrant
Scour:	8 Good: Low flow with heavy silt in channel
Approach:	6 Fair: Minor settlement of hot mix asphalt in both approaches
Approach Shoulders:	N/A: No approach shoulders, sidewalks, or curb and gutter

Recommended repairs

Based upon the review of the field conditions, there are two alternatives:

Alternative 1:

- Steel Repairs (Requires engineering design and plans)
 - o Bolt/weld steel plates to gussets with heavy deterioration
 - o Grind/punch out rivets and replace with bolts on repaired plates and members
 - Cut and weld built-up c-channel to lap gap in truss channel
 - Weld plates to lap holes in angles
- Seal or Replace Hot Mix Asphalt
 - Seal block cracking in surface and end joints
 - o or scarify hot mix asphalt and place thin, composite deck (Requires engineering design and plans)
- Railing Repair
 - Secure loose fasteners
 - Replace segments with collision damage
- Timber Repair
 - Inject epoxy/wood glue into fascia beam with shake
- Paint
 - o Blast and paint full steel structure
- Approach
 - Replace 5' of both approaches

Note: Estimates do not include design and construction administration

Alternative 2 (Requires engineering design and plans):

- Superstructure
 - Replacement
- Substructure
 - o Scarify and repair bearing concrete & delaminated concrete
- Approach
 - Replace 5' of both approaches

Note: Estimates do not include design and construction administration



Field Review Findings Deck

Approaches

The hot mix asphalt approach pavements are in fair condition with minor settlement in both approaches. The west approach has alligator cracking with two hot mix asphalt cold patches along tire pathway. The east approach has alligator cracking and spalling within 30' of the East reference line.

Deck Surface

The deck surface is not visible and is based on the hot mix asphalt overlay surface. In general, the surface is in fair condition. There is block cracking approximately every 10' in-line with the floor beams and centerline of the roadway.

Deck Underside

The timber deck underside is in good condition with one (1/4'') shake noted in the south fascia.

Joints

There are reflective cracks at the reference lines for both ends of the structure with no signs of leaking.

Railing

The thru truss acts as a railing for traffic and angles are bolted to the superstructure for pedestrian safety. Some bolts are loose and there are few areas of collision damage.

Superstructure

Floor-Beams

The floor-beams are in serious condition based on the section loss at the connection to the truss. There is some pack rust on the longitudinal stiffeners with minor loss of section to the rolled section. The paint is also peeling, suggesting the surface was not properly prepped when previously painted.

Truss

The superstructure has two thru trusses that are in serious condition based on the section loss at the bearings and gusset plates. Load analysis required a reduction of the posting based on severe loss of section at the bearings. Otherwise, the superstructure is in fair condition with paint peeling throughout.

Gussets

The upper gussets are in good condition with minor paint peeling at the corners. The lower gussets are in serious condition with distortion from moment being transferred through a single plate and holes through the gusset plates at all bearings and panel point L1 on the north side.

Substructure

Abutments

The concrete cantilever abutments are supported by steel piles and are in fair condition. There is a large spall in the Southwest quadrant, however, the concrete has delaminated and spalled off. The surface of both abutments has moderate scaling, but function as designed.



Name: IMG_0096 (1024x767) Description: L1 south side floor beam connection



Name: IMG_0097 (1024x767) Description: Structure 7 dimensions





Name: IMG_0098 (1024x768) Description: Deck bottom



Name: IMG_0099 (1024x768) Description: Timber slab





Name: IMG_0100 (1024x767) Description: Dimensions



Name: IMG_0102 (1024x767) Description: Structure 7 dimensions





Name: IMG_0103 (1024x768) Description: Split in timber fascia



Name: IMG_0104 (1024x768) Description: East abutment





Name: IMG_0105 (1024x768) Description: West abutment



Name: IMG_0106 (1024x768) Description: L1 North side, hole





Name: IMG_0107 (1024x768) Description: L1 North side, hole



Name: IMG_0108 (1024x767) Description: L1 north side, hole





Name: IMG_0202 (1024x768) Description: Posting sign, west side



Name: IMG_0203 (1024x768) Description: Deck surface





Name: IMG_0204 (1024x768) Description: West approach



Name: IMG_0205 (1024x767) Description: East approach





Name: IMG_0206 (1024x768) Description: South elevation



Name: IMG_0207 (1024x767) Description: Dimensions





Name: IMG_0208 (1024x768) Description: L0 South side, holes in bearing



Name: IMG_0209 (1024x767) Description: Bearing L0 south side





Name: IMG_0210 (1024x767) Description: L0 south side, hole



Name: IMG_0211 (1024x767) Description: Hole thru plate





Name: IMG_0213 (1024x767) Description: Dimensions



Name: IMG_0214 (1024x767) Description: L1 south side





Name: IMG_0215 (1024x767) Description: L1 south side



Name: IMG_0216 (1024x767) Description: L1 south side





Name: IMG_0217 (1024x767) Description: L1 south side



Name: IMG_0218 (1024x767) Description: L0 north side





Name: IMG_0219 (1024x767) Description: L0 north side



Name: IMG_0220 (1024x767) Description: L1 north side





Name: IMG_0221 (1024x767) Description: L1 north side



Name: IMG_0222 (1024x767) Description: L1 north side





Name: IMG_0223 (1024x767) Description: L1 north side



Name: IMG_0224 (1024x767) Description: Simple span timber





Name: IMG_0225 (1024x767) Description: Dimensions



Name: IMG_0226 (1024x768) Description: Spall in south side of west abutment





Name: IMG_0227 (1024x767) Description: U1 south side



Name: IMG_0228 (1024x767) Description: U2 south side





Name: IMG_0229 (1024x767) Description: U3 south side



Name: IMG_0230 (1024x767) Description: U4 south side





Name: IMG_0231 (1024x767) Description: U5 south side



Name: IMG_0232 (1024x767) Description: U6 south side





Name: IMG_0233 (1024x767) Description: U7 south side



Name: IMG_0234 (1024x767) Description: U1 north side





Name: IMG_0235 (1024x767) Description: U2 north side



Name: IMG_0236 (1024x767) Description: U3 north side





Name: IMG_0237 (1024x767) Description: U4 north side



Name: IMG_0238 (1024x767) Description: U5 north side





Name: IMG_0239 (1024x767) Description: U6 north side



Name: IMG_0240 (1024x767) Description: U7 north side





Name: IMG_0241 (1024x767) Description: L4 South side



Name: IMG_0242 (1024x767) Description: L4 south side





Name: IMG_0243 (1024x767) Description: L4 south side



Name: IMG_0244 (1024x767) Description: L4 north side





Name: IMG_0245 (1024x767) Description: L4 north side



Name: IMG_0246 (1024x767) Description: North channel





Name: IMG_0247 (1024x767) Description: South channel



Name: IMG_0248 (1024x715) Description: Clear roadway





Name: IMG_0249 (1024x767) Description: L2 south side



Name: IMG_0250 (1024x767) Description: L3 south side





Name: IMG_0251 (1024x767) Description: L2 north side



Name: IMG_0252 (1024x767) Description: L3 North side





Name: IMG_0253 (1024x767) Description: Dimensions



Name: IMG_0254 (1024x767) Description: Dimensions



		2025	Į			BRIDGE COST E	STIMATE WO	RKSHEET					REV. 02/5/2025	
Anticipated yea	r of construction:	2028	+			- CPM, RE	HAB, REPLAC	E -			-	DATE:	2/5/2025	
Min. annual Infl Max. annual Infl	ation Limit: ation Limit:	3.00%	LOCATION:	Algonquin Ave	e over	Woodland Lagoon		LENGTH 54.0	Out to Out 18.0	Curb to Curb 14.7	E	NGINEER:	V. Guadagni	
OWNED:		Lakosida Bark Sub	PRIMARY WORK ACTIVITY	/ Bri	dge Replacem	ent	EVICT		072	PET	STRUC	TURE ID:	#NI/A	
REGION:		Metro	PR:	#N/A M	P: #N/A		EXISTING CL	EAR ROADWAY:	794	FT	Ы	KIDGE ID.	#IV/A	
TSC:		#N/A					PROPOSED CL	SED DECK AREA: EAR ROADWAY:	1,590.0 1,440.0	SFT FT	S	TR. TYPE: #	N/A	
		wo	RK ACTIVITY	lincrose	MDOT Brid	ge Design Guides		UANTITY	UNIT	UNIT COST	llead	(5	TOTAL	
NEW BRIDGE	Single or Multipl	e Spans, Grade Sepa	aration	(increas	(add demo	, approach, MOT)	addic requirementa)		SFT	507	507	/SFT	nce projection to 2020)	
	Single Span, Ov Multiple Spans.	ver Water Over Water		Length < 100ft Length > 100ft	(add demo (add demo	, approach, MOT) , approach, MOT)		1,590.0	SFT	605 544	605 544	/SFT /SFT	\$961,632.00	
	Precast Culvert			Length < 40ft	(add demo	, approach, MOT)			SFT	654	654	/SFT		
	Railroad				(add demo	, approach, MOT)			SEI	465	465	/SF1		
NEW SUPERS	New Superstruct	ture. Grade Separati	00	(in	1 remove exis	t deck/super: add MOT & apr	proach)		SET	398	398	/SFT		
	New Superstruct	ture, Over Water		(in	cl. remove exis	t deck/super; add MOT & app	proach)		SFT	263	263	/SFT		
	New Superstruc	ture, Combined		(in	cl. remove exis	t deck/super; add MOT & app	proach)		SEI	277	277	/SFT		
WIDENING	Structure Wider	nina. ft		(in	deck/super/	sub widening, add approach t	transition)		SET	1005	1005	/SET		
				(oub widdning, ddd approdorr (anonony		0.1	1000	1000	/0/ 1		
NEW DECK	New Bridge Dec	k & Barrier		(in	l. remove exis	t deck/railing, add approach, l	MOT)		SFT	160	160	/SFT		
DEMOLITION														
	Entire Structure	, Grade Separation						070.0	SFT	46	46	/SFT	\$440,400,00	
	Entire Structure	, Over water						972.0	SFI	115	115	/SF1	\$112,129.92	
DECK REPAIR	/ TREATMENT	S		(in		f conlocoment)			ET	1066	1066	/ET		
	Concrete Brush	Block / Curb Patch		(in)	l. hand chippi	ng and formwork)			FT	64	64	/FT		
	Concrete Barrie	r Patch		(in	cl. hand chippi	ng and formwork)			SFT	152	152	/SFT		
	Deep Overlay	Patch		(in (in	cl. joint repl & I	ng) hydro)			SFT	54	54	/SFT		
	Epoxy Overlay			(in	l. warranty)				SYD	69	69	/SYD		
	Expansion Joint Expansion Joint	Replacement		(re (in	move and repi cl. removal)	ace elastomeric gland)			FT	192	192	/F1 /FT		
	Full Depth Patch	n .							SFT	154	154	/SFT		
	Healer / Sealer HMA Overlav w	ith WP membrane		(pe	netrates crack	s in bridge deck)			SYD	25	25	/SYD		
	Overlay Remova	al							SYD	32	32	/SYD		
	(Latex Concrete (Epoxy Overlay	Surface Removal) Removal)							SYD	32	32	/SYD		
	(HMA Surface F	Removal)							SYD	20	20	/SYD		
	Reseal Bridge J Shallow Overlay	oints		(in	:L ioint repl & I	hydro)			FT	42	42	/FT /SET		
	,			(.)/	1							
SUPERSTRUC	Bearing Realign	ment / Replacement		(in	l temporary s	upports)			FA	6678	6678	FA		
	Heat Straighten	ing		(in	cl. clean and c	oat)			EA	109426	109426	EA		
	Pack Rust Repa Paint - Complete	air a		(gr	eater than 3/8'	' separation)			FT	723	723	/FT /SET		
	Paint - Partial / S	Spot / Zone		(in	cl. clean & coa	-, t - \$20k minimum)			SFT	52	52	/SFT		
	PCI Beam End	Blockout		(in	cl. temporary s	upports)			EA	12617	12617	EA		
	Structural Steel	Repair		(Ini	sed on 6ft rep	air length)			EA	9497	9497	EA		
	Structural Steel	Repair - Stiffener		(in	cludes each si	de of beam)			EA	3173	3173	EA		
SUBSTRUCTU	JRE REPAIR													
	Substructure Pa Substructure Re	atching		(m (in	easured x 2) r	eplace if repair area > 30%			CFT	453	453 538	/CFT /CFT		
	Substructure Ho	prizontal Surface Seal	er	(n. tomportary c	apporto, oxouration,			SYD	111	111	/SYD		
	Temporary Sup	ports		(ac	d Structural S	teel Repair - Stiffener for ea st	teel beam)		EA	7481	7481	EA		
MISCELLANE	OUS	crate Block Suptom /	ACB)						SAD	402	402	/evn		
	Concrete Surfac	crote block System (ce Coating	nob)						SYD	+02 59	59	/SYD		
	Culvert Cleanou	t			uotural'	roppir)			FT	57	57	/FT		
	Metal Mesh Par	iels		(st (48	width, max 6	-6" length)			SFT	42	42	/FT		
	Pressure Relief	Joint		(us	e when appro	ach concrete roadway exceed	ls 1,000ft)		FT	190	190	/FT		
	Silane Treatmen	nt		(as	netrating seale	er for concrete surfaces)	and clure)		SFT	6	-+03	/SFT		
	Slope Protection	n Repairs		0-	-			10	SYD	301	301	/SYD	\$7 F00 00	
	Other			26	Clion Tub revie	w process		1.0	LSUW	0	7500	LSUW	\$7,500.00	
									ST	RUCTURE CONSTR	UCTION B	UDGET	\$1,073,762	
ROAD WORK														
	Approach Paver	nent, 12" RC & Gutter		(in	cl. removal; ad	d curb, gutter, guardrail) 40' e	ea. end	266.7	SYD	1015	1015	/SYD	\$270,625.71	
	Guardrail Ancho	a Gutter prage to Bridge		(in)	ch quadrant)	J ea. quadrant		4.0	EA	4547	4547	/FI /EA	\$2,753.92 \$18,188.41	
	Guardrail			(in	cl. removal) <	200ft beyond reference line		200.0	FT EA		41	/FT	\$8,200.00	
	Guardrail Termi Roadway Appro	ach Work		(ea (be	cn quadrant) yond approacl	h pavement)		4.0	LSUM		3900	/EA LSUM	\$15,600.00	
	Utilities								LSUM			LSUM		
TRAFFIC CON	TROL		Unit Cost to be determined	by Region or TS	C Traffic & Sa	lfety								
	Part Width Con	struction							LSUM			LSUM	-	
	Temporary Traff	fic Signals							EA set			/EA /set		
	RR Flagging							4.2	LSUM		¢00.000 °	LSUM	ê00 000 00	
	Delour							1.0	LOUM		⇒∠υ,000.0	LOUM	\$20,000.00	
								REL	ATED ROA	D/TRAFFIC CONSTR	UCTION B	UDGET	\$335,368	
CONTINGENC	Y		(10% - 20%) (use higher co	ntingency for sm	all projects)			15	%		\$1,409.12	29.96	\$211.369	
MOBILIZATION	N		(estimate at 10%)		. ,,			10	%		\$1,620,4	99.46	\$162,050	
						(Do	oes not include PE or CE)			TOTAL CONSTR	JCTION B	UDGET	\$1,782,549	

I 5.63 % Equaivalent Inflation % CE % PE % PE-S Inflation Budget: CE BUDGET PE BUDGET PE-S BUDGET \$100,389 \$0 \$0 \$0 \$0

(Refer to programming guidelines or Suggested PE &CE tab in Bridge Cost Estimating Worksheet for CE,PE & PE-S)